

APPENDIX D

COMMUNITY CHARACTER-RELATED DOCUMENTS

Appendix D-1
Photographs of Hills South Parcel/Kracke Property



**PHOTOGRAPHS OF IMPACTED AREAS
HILLS SOUTH PARCEL/KRACKE PROPERTY**

Source: NYSGIS Orthoimagery Program, 2013
Scale: 1 inch = 1,000 feet



**The Hills
at
Southampton**

Draft EIS



1. View of scrap metal in center portion of subject property



2. View of playset and debris in center portion of subject property



3-1. View of jetski in center portion of subject property



3-2. View of ATV tracks in center portion of subject property



3-3.View of debris in center portion of subject property



4.View of debris in center east portion of subject property



5.View of garbage bags and debris in center portion of subject property



6.View of garbage bags and debris in center portion of subject property



7-1. View of shingles and construction debris in center north portion of subject property



7-2. View of rubber construction debris in center portion of subject property



7-3. View of concrete and construction debris in center north portion of subject property



7-4. View of insulation and construction debris in center north portion of subject property



7-5. View of glass and plastic debris in center north portion of subject property



8-1. View of shingles in center north portion of subject property



8-2. View of miscellaneous plastic and wood debris in center north portion of subject property



9-1. View of furniture in northeast portion of subject property



9-2. View of large pile of shotgun shells in northeast portion of subject property



9-3. View of miscellaneous debris in northeast portion of subject property



10-1. View of aluminum siding in northeast portion of subject property



10-2. View of miscellaneous debris in northeast portion of subject property



11. View of debris in north center portion of subject property



12. View of pvc pipe and construction debris in north center portion of subject property



13. View of shotgun shells and clay pigeons in north center portion of subject property



14. View of tire and debris in center west portion of subject property



15. View of construction debris in center west portion of subject property



16. View of miscellaneous debris in center west portion of subject property



17. View of furniture in center portion of subject property



18. View of furniture in south portion of subject property



19. View of 55 gallon drum in south portion of subject property



20. View of miscellaneous metal debris in south portion of subject property



**PHOTOGRAPHS OF IMPACTED AREAS
KRACKE PARCEL**

**The Hills
at
Southampton**



Source: NYSGIS Orthoimagery Program, 2013
Scale: 1 inch = 350 feet



PDD Application



1. View of debris pile in southern portion of the property.



2. View of debris pile in southern portion of the property.



3. View soil and sand pile along the dirt trail.



4. View cleared area and debris pile next to dirt trail.



5. View of debris on the east side of the dirt trail in the central portion of the property.



6. View of debris on the east side of the dirt trail in the central portion of the property.



7. View of landscape debris in the northern portion of the property.



8. View looking south at landscape debris in the northern portion of the property.



9. View looking north at construction debris in the northern portion of the property.



10. View looking west along dirt trail in the northern portion of the property.



11. View looking north at landscape debris in the northern portion of the property.



12. View looking west at landscape debris in the northern portion of the property.



13. View of landscape debris in the central area of the northern portion of the property.



14. View of debris in the central area of northern portion of the property.



15. View landscape and construction debris in the central area of the northern portion of the property.



16. View of landscape debris in the central area of the northern portion of the property.



17. View of debris pile in northwestern portion of the property.



18. View of debris pile in northwestern portion of the property.



19. View of debris pile in northwestern portion of the property.



20. View of debris pile in northwestern portion of the property.



21. Hunting stand in the northwestern portion of the property.



22. View of farming debris and dilapidated trailer in southern portion of subject property.



23. View native soil piles and natural debris in southern portion of subject property.



24. View of construction debris in the southeastern portion of the property.



25. View of construction debris and litter in the southeastern portion of the property.



26. View of construction debris and litter in the southeastern portion of the property.



27. View of the southern portion of the dirt trail on the subject property.



28. View cleared area and natural debris pile next to dirt trail in the southeastern portion of the property.